

Link do produktu: <https://sklep-agrotur.pl/filtr-oleju-filtron-op-537-p-19406.html>



## FILTR OLEJU FILTRON OP 537

Cena	<b>25,00 zł</b>
Dostępność	<b>Dostępny</b>
Czas wysyłki	<b>24 godziny</b>
Numer katalogowy	<b>4776</b>
Kod producenta	<b>OP 537</b>
Kod EAN	<b>5904608005373</b>
Producent	<b>FILTRON</b>

### Opis produktu

FILTR OLEJU FILTRON OP 537



WYMIARY (mm):

- A 76.5
- B 71.5
- C 62.5
- G 3/4-16 UNF
- H 96.5

By-pass Valve Yes

Anti-Drain Valve Yes

Anti-siphon Valve No

## ZASTOSOWANIE

Alfa Romeo 145, 146, 147, 155, 156, 164, 166;

Ferrari Tractors;

Fiat Brava, Bravo, Cromar, Ducato, Palio, Punto I, Siena, Tempra, Tipo, Uno;

Lancia;

Moskvitch;

Same;

Seat;

Zastava

## ZAMIENNIKI:

Numery części OEM

AC X18; AC X19; AC X501; AC X532; AC X533; ALCOFILTER SP0907; ALCOFILTER SP1087; ALCOFILTER SP907; ALCOFILTER SP928; ALFA 116440603000; ALFA 60507080; ALFA 60574554; ALFA 605745540; ALFA 7773854; ARMAFIL O1091003; ARMAFIL O791007; BOSCH 0451103096; BOSCH 0451103151; BOSCH 045110315130N; BOSCH 0451103170; BOSCH 0451103241; BOSCH 045110324130N; BOSCH 0451103255; BOSCH 0451103286; BOSCH 045110328644N; BOSCH 0451103351; BOSCH 0451103352; BOSCH 0451103356; BOSCH 0451203151; BOSCH 0451203155; BOSCH 451103096; BOSCH 451103151; BOSCH 451103170; BOSCH 451103241; BOSCH 451103255; BOSCH 451103286; BOSCH 451103351; BOSCH 451103352; BOSCH 451103356; BOSCH 451203151; BOSCH 451203155; BOSCH 9451103100; BOSCH F026408709; BOSCH P3351; BOSCH P3352; CHAMP LS115; CHAMP LS145; CHAMP LS187; CHAMP LS235; CHAMPION C104; CHAMPION C106; CHAMPION C106606; CHAMPION C112; CITRO 1109W7; CLEANF DO1816; CLEANF DO238; CLEANF DO239; CLEANF DO321; COMLINE EOF049; COOPE Z121; COOPE Z1346; COOPE Z1458; COOPE Z1468; COOPE Z904; COOPERSFIA FT4925; COOPERSFIA FT4949; COOPERSFIA FT5056; COOPERSFIA FT5582; COOPERSFIA FT5682; CROSL 2022; CROSL 2043; CROSL 2047; CROSL 2220; CROSL 484; CROSL 5291; DELPHI EFL504; DELPHI EFL965; DELPHI FX0082; DELPHI FX0134; DELPHI FX0148; DELPHI LK1021; DONIT 4310110; DONIT 4310112; DONIT 4310116; DONIT 4310153; FIAT 4212109; FIAT 4228326; FIAT 4339509; FIAT 4356500; FIAT 4363484; FIAT 4371581; FIAT 4382101; FIAT 4394463; FIAT 43944630; FIAT 4434790; FIAT 4434792; FIAT 4434895; FIAT 4449040; FIAT 46805830; FIAT 46805831; FIAT 5939831; FIAT 5951865; FIAT 60507080; FIAT 60574554; FIAT 60810474; FIAT 60810709; FIAT 71736160; FIAT 71736166; FIAT 71754231; FIAT 7581562; FIAT 7689285; FIAT 7773854; FILTREC ZP523C; FILTREC ZP568A; FILTRON OP535; FILTRON OP537; FORD 5010963; FORD 5012555; FORD 5019918; FRAD 101905110; FRAD 101906110; FRAM PH2956; FRAM PH3682; FRAM PH4482; FRAM PH9105; FRAM PH9733; GUELDNER Z494; HEN H14W13; HEN H40W01; KNECHT OC106; KNECHT OC137; KNECHT OC1371; KNECHT OC501; KNECHT OC96; KOLBENSCHM 1530S; KOLBENSCHM 2830S; LAMBO 244191401; LAURA ELH4138; LAURA ELH4140; LAUTR ELH4138; LAUTR ELH4140; LAUTR ELH4328; LUCAS ELEC EDL179; MANN W11264; MANN W7134; MANN W7134x; MANN W7143; MANN W7182; MAPCO 61007; MAPCO 61126; MECAFILTER ELH4138; MECAFILTER ELH4140; MECAFILTER ELH4328; MOTIP VFL197; MOTOK 1; MOTOK 244191400; MOTOK 244191401; MOTOK 30738096; MOTOK 452040901; MOTOK 8671002040; MOTOK 8671002044; MOTOK 92832567; MOTOK 92835417; MOTOK 92835467; MOTOK 92835483; MOTOK AP1021; MOTOK CV304; MOTOK ELH4138; MOTOK ELH4140; MOTOK EXL141A; MOTOK EXL166; MOTOK F115; MOTOK FB2074; MOTOK FB5311; MOTOK FB5321; MOTOK FT129; MOTOK FT378; MOTOK GL385; MOTOK GP3682; MOTOK HOF214; MOTOK HOF258; MOTOK MAP122; MOTOK MAP188; MOTOK MOF90X; MOTOK OF3682; MOTOK OL161; MOTOK OL175; MOTOK OL341; MOTOK PMFL28; MOTOK PP362; MOTOK PP478; MOTOK PP88; MOTOK PSL44; MOTOK R354; MOTOK R409; MOTOK SO319; MOTOK SO325; MOTOK SO354; MOTOK SP4395; MOTOK SP4402; MOTOK VFL197; MOTOK VFL221; MOTOK W71298; MOTOK W92099; MOTOK WO390; MOTOK WO420; MOTOK Z166; MOTOK Z175; MOTOK Z445; MOTOK Z84; MOTOK ZM133; MOTOK ZP523C; MOTOK ZP568A; MOTORCRAFT EFL154; MOTORCRAFT EFL283; MOTORCRAFT EFL9048; MOTORCRAFT EFL9058; NISSAN 1520860400; PBR BC1091; PBR BC1176; PBR BC1291; PBR BC1328; PBR BC1329; POWERP PMFL123; PURFLU LS194FIAT; PURFLU LS349; PUROLATOR L17822; PUROLATOR L27276; QUINTON HA QOF5311; QUINTON HA QOF5321; QUINTON HA QOF5457; REMKAFLEX Z101; RENAULT 7701415064; SAKURAAUTO C2211; SEAT 0003938626; SEAT 0004449040; SEAT 3938626; SEAT 4449040; SEAT SE700030288A; SOFIMA S1410R; SOFIMA S1610R; SOFIMA S4210R; SOFIMA S5210R; SOFIMA S5700R; SOFIMA S5710R; SOFIMA S9430R; SPIDAN MOF90X; TECNOCAR R124; TECNOCAR R125; TECNOCAR R161; TECNOCAR R175; TECNOCAR R349; TEHO 4121; TEHO 4334; TEHO OK75; TJFIL FB5321; TJFIL FB5457; UFI 2316600; UFI 2317100; UFI 2317200; UFI 2317300; UFI 2317500; UFI 2321600; UFI 2344500; UFI 2344800; UFI GFE173; UNI GFE180; UNI GFE23; UNI GFE272; UNI GFE299; UNICO F. LI10954; UNICO F. LI71004; UNICO F. LI99536; VW 0003938626; VW 0004449040; VW 3938626; VW 4449040; VW SE700030288A;